




**ENERGIZING
INNOVATION**
www.hydroevent.com







Bearing Failures


- Interesting subject.
- Normally not by choice.
- Solving a bearing failure can become priority # 1
- Imagine when multiple bearing failures occur.

Owned & Produced by:



Presented by:


Media Partners:





**ENERGIZING
INNOVATION**
www.hydroevent.com







Bearing Failure Consequences

- Adding to project duration and costs
- Very expensive down time when unplanned event.
- Mess with personnel vacation plans
- Can create frustration

Owned & Produced by:


Presented by:


Media Partners:

Cases Review

Project Fictive name	Type	# of bearings	Damaged bearing	Event year	Bearing life (years)	Power (MW)	Causes
Horse Creek	Suspended	3	LGB	1997	0	8	Bracket Assembly
Sea Falls	Overhang	3	TGB	2001	30	>300	Head cover flatness
Thundering	Suspended	3	Thrust	2000	0	30	Alignment, Bracket flatness
Beauchamp	Suspended	3	Thrust	2001 2005	0.5	>100	Design, Combination
South Plain	Overhang	3	Thrust TGB	2000 2006	0	>300	Design, Manufacturing Operation
Wolfgang	Suspended	2	Thrust	2000	5	<10	Alignment Verticality
Hope Bay	Overhang	2	Thrust	1996	0.5	>100	Runout, Balancing
Stone Falls	Suspended	3	Thrust	2013	0	15	Design, Manufacturing Assembly
Magnan	Suspended	2	UGB	2003	0	>300	Vibration, Resonance

Cases Review

Case #	Project Fictive name	Type	Damaged bearing	Bearing life (years)	Power (MW)	Causes
1 →	Horse Creek	Suspended	LGB	0	8	Bracket Assembly
2 →	Sea Falls	Overhang	TGB	30	>300	Head cover flatness
3 →	Thundering	Suspended	Thrust	0	30	Alignment, Bracket flatness
	Beauchamp	Suspended	Thrust	0.5	>100	Design, Combination
	South Plain	Overhang	Thrust TGB	0	>300	Design, Manufacturing Operation
4 →	Wolfgang	Suspended	Thrust	5	<10	Alignment Verticality
	Hope Bay	Overhang	Thrust	0.5	>100	Runout, Balancing
5 →	Stone Falls	Suspended	Thrust	0	15	Design, Manufacturing Assembly
	Magnan	Suspended	UGB	0	>300	Vibration, Resonance

HydroVision
INTERNATIONAL

ENERGIZING
INNOVATION
www.hydroevent.com

WORLD'S
LARGEST
HYDRO EVENT
20 YEARS
STRONG

Bearing Failures

Different types of bearing failures,

This presentation is mainly for wiped bearings...

...with causes related to assembly and alignment.


Owned & Produced by:



Presented by:



Media Partners:




HydroVision
INTERNATIONAL


ENERGIZING
INNOVATION

WORLD'S
LARGEST
HYDRO EVENT
20 YEARS
STRONG


Case # 1 - Horse creek

This guide bearing had multiple failures.
Why?







**ENERGIZING
INNOVATION**
www.hydroevent.com








Case # 1 - Horse creek

- 3 guide bearing failures at start-up
- Minor fixes had been done, but did not solve it
 - Bracket re-centering
 - Pole short-circuited turn fixed


Owned & Produced by:


Presented by:


Media Partners:








**ENERGIZING
INNOVATION**
www.hydroevent.com








Case #1 - Horse creek


Method used for diagnostic


- Turbine bearing and shaft seal out
- Lower guide bearing out
- Rotational checks,
 - airgap sensors for rotor/stator sweeps
 - precision level on shaft
 - dial indicators and micrometer readings
 - runner seal clearances


Owned & Produced by:


Presented by:


Media Partners:

















Case #1 - Horse creek


Alignment results


- Verticality deviation 23 mils/ft !! (1.9 mm/m)
 - Not sufficient cause for bearing failure
- Stator / rotor concentricity 50 mils (2X CEATI tol.)
 - Create additional radial force
 - Not fixed for not worsening runner clearances
- Runout at TGB 17 mils (within CEATI tolerance)
 - Reduced at 9 mils as additional precaution
- Seating flange for LGB with flatness error of 7 mils


Owned & Produced by:


Presented by:


Media Partners:














Case # 1 - Horse creek

Perpendicularity and flatness check







**ENERGIZING
INNOVATION**
www.hydroevent.com




Case # 1 - Horse creek


Perpendicularity and flatness check










Flatness error of 0.007 in.


Owned & Produced by:


Presented by:



Media Partners:








**ENERGIZING
INNOVATION**
www.hydroevent.com





Case # 1 - Horse creek



Flatness error came from bracket distortion due to wrong shimming










Case # 1 - Horse creek


After correction of shims under bracket arms









Good perpendicularity and flatness within 3 mils


* Local surface defect corrected with a shim of 4 mils


Owner & Produced by


Presented by


Media Partners

















Case # 1 - Horse creek



Conclusion:

- The most important correction for that project was to fix the flatness of the seating surface where the guide bearing is bolted, preventing unwanted distortion of the bearing.
- The fixed bearing ran for 25 years until 2012 when the unit was stopped for a major overhaul.

Owner & Produced by


Presented by


Media Partners








HydroVision
INTERNATIONAL

ENERGIZING
INNOVATION
www.hydroevent.com

WORLD'S
LARGEST
HYDRO EVENT
20 YEARS
STRONG

Case # 2 Sea Falls


Shell type bearing
68" Dia x 25" high
In 6 sections



Owned & Produced by:



Presented by:



Media Partners:



HydroVision
INTERNATIONAL

ENERGIZING
INNOVATION
www.hydroevent.com

WORLD'S
LARGEST
HYDRO EVENT
20 YEARS
STRONG

Case # 2 Sea Falls


DIAGNOSTIC

- Unit alignment checked and OK
 - ✓ Runout
 - ✓ Concentricity
 - ✓ Verticality
- Seating surface for Turbine Bearing, not OK
 - ✓ Flatness deviation of 0.014"

Owned & Produced by:





Presented by:



Media Partners:











Case # 2 Sea Falls

Two high points
and two low points
around the
circumference




Owned & Produced by:



Presented by:



Media Partners:


















Case # 2 Sea Falls


- Under axial deformation of 0.014"
- Babbitt face varies up to 0.008" (0.20 mm)
- Bearing not designed to work in that condition
- It takes only 3 tons or 1 bolt on each side to deform it.





Owned & Produced by:


Presented by:


Media Partners:

















Case # 2 Sea Falls


SOLUTIONS / CONCLUSION


- If major overhaul, machining of stationary components probably required.
- For a repair, we added shims of different thicknesses around the circumference of the seating flange, to make it flat (within 0.005")
- That repaired bearing may possibly live for 30 years, and already ran for 13 years.


Owned & Produced by:


Presented by:


Media Partners:















Case # 3 - Thundering

This thrust bearing had multiple failures.
Why?















Case # 3 Thundering


SUMMARY


- Repetitive bearing failure at start-up
- Bent surface under the thrust bearing base ring plate
 - flatness error of the order of 0.40 mm (0.016")
 - Leading to non-uniform loading of the bearing
 - Visible on wiped bearing pattern
- Recommended solution was to readjust shimming of the upper bracket legs, and control surface flatness.


Owned & Produced by:


Presented by:


Media Partners:












Case # 4 Wolfgang


SUMMARY





- Small suspended machine similar to case no. 3
- Thrust bearing failure after 5 years.
- Upper bracket was misaligned, creating non-uniform load on the bearing. More load on one side.

Interesting fact

- Since start-up, the bearing temperature increased 2°C every year (same month) up to failure.

Owned & Produced by:


Presented by:


Media Partners:







ENERGIZING
INNOVATION

www.hydroevent.com



Case # 5 Stone Falls



Owned & Produced by:


Presented by:


Media Partners:








ENERGIZING
INNOVATION

www.hydroevent.com



Case # 5 Stone Falls



Bottom side of the rotating ring has 4 radial grooves


Owned & Produced by:


Presented by:



Media Partners:







ENERGIZING
INNOVATION
www.hydroevent.com




Case # 5 Stone Falls








Babbitt wiped

Owned & Produced by:



Presented by:


Media Partners:




ENERGIZING
INNOVATION
www.hydroevent.com




Case # 5 Stone Falls





Solution for that unit




- No change on alignment
- Minimum cut in Babbitt
- Hand scraping of the Babbitt surface
 - Rubbing against actual thrust collar assembly for finding high spots, instead of flat marble
- Redistribution of springs, shorter springs near edges

Owned & Produced by:


Presented by:


Media Partners:














Case # 5 Stone Falls




Final result

- Thrust bearing temperature from 60s to 50s °C
- Inspection of bearing after commissioning revealed a Babbitt surface in perfect condition.

Owned & Produced by: 


Presented by: 


Media Partners:    








Bearing Failures Prevention

Simple: good design, manufacturing, installation and commissioning ☺ ... plus maintenance and monitoring.


Owned & Produced by: 

Presented by: 

Media Partners:    




**ENERGIZING
INNOVATION**
www.hydroevent.com




Bearing Failures Prevention





Installation tips


- Proper load distribution on bracket legs (no soft foot)
- Check surface flatness under thrust bearing (if applicable)
- Check flatness of seating surfaces for guide bearing
- Proper alignment with rotational checks
- Check bearings and shaft parallelism

Owned & Produced by:



Presented by:


Media Partners:




**ENERGIZING
INNOVATION**
www.hydroevent.com




Bearing Failures Prevention





How To Check bearings and shaft parallelism?


- Check unit axis verticality and level of brg seating flange
- Dial on shaft to check seating flange perpendicularity
- Get top and bottom clearances when possible
 - Rule of thumb, 0.0015" maximum difference between top and bottom centers.

Owned & Produced by:



Presented by:


Media Partners:




**ENERGIZING
INNOVATION**
www.hydroevent.com




Bearing Failures Prevention





Preventive maintenance & Monitoring

- Periodic inspection of thrust bearing in some cases.
- Periodic oil sampling
- Trending of temperature over consecutive years

Owned & Produced by:


Presented by:


Media Partners:



**ENERGIZING
INNOVATION**
www.hydroevent.com



Presented

on July 24, 2014

by

Dany Lessard, Eng. Msc

dany.Lessard@hydroexpertise.com

mobile: 514-702-4937


Hydro Expertise

Booth no 358

Owned & Produced by:


Presented by:


Media Partners:

